Office of the Secretary, HUD

from which occupants have been relocated; or, for an exterior hazard reduction activity, where it is easily read 20 feet (6 meters) from the edge of the hazard reduction activity worksite. Each warning sign shall be as described in 29 CFR 1926.62(m), except that it shall be posted irrespective of employees' lead exposure and, to the extent practicable, provided in the occupants' primary language.

§35.1350 Safe work practices.

- (a) Prohibited methods. Methods of paint removal listed in §35.140 shall not be used.
- (b) Occupant protection and worksite preparation. Occupants and their belongings shall be protected, and the worksite prepared, in accordance with §35.1345. A person performing this work shall be trained on hazards and either be supervised or have completed successfully one of the specified courses, in accordance with §35.1330(a)(4).
- (c) Specialized cleaning. After hazard reduction activities have been completed, the worksite shall be cleaned using cleaning methods, products, and devices that are successful in cleaning up dust-lead hazards, such as a HEPA vacuum or other method of equivalent efficacy, and lead-specific detergents or equivalent.
- (d) De minimis levels. Safe work practices are not required when maintenance or hazard reduction activities do not disturb painted surfaces that total more than:
- (1) 20 square feet (2 square meters) on exterior surfaces;
- (2) 2 square feet (0.2 square meters) in any one interior room or space; or
- (3) 10 percent of the total surface area on an interior or exterior type of component with a small surface area. Examples include window sills, baseboards, and trim.

[64 FR 50218, Sept. 15, 1999, as amended at 69 FR 34275, June 21, 2004]

§ 35.1355 Ongoing lead-based paint maintenance and reevaluation activities.

(a) Maintenance. Maintenance activities shall be conducted in accordance with paragraphs (a)(2)–(6) of this section, except as provided in paragraph (a)(1) of this section.

- (1) Maintenance activities need not be conducted in accordance with this section if a lead-based paint inspection indicates that no lead-based paint is present in the dwelling units, common areas, and on exterior surfaces, or a clearance report prepared in accordance with §35.1340(a) indicates that all lead-based paint has been removed.
- (2) A visual assessment for deteriorated paint, bare soil, and the failure of any hazard reduction measures shall be performed at unit turnover and every twelve months.
- (3) (i) Deteriorated paint. All deteriorated paint on interior and exterior surfaces located on the residential property shall be stabilized in accordance with §35.1330(a)(b), except for any paint that an evaluation has found is not lead-based paint.
- (ii) Bare soil. All bare soil shall be treated with standard treatments in accordance with §35.1335(d) through (g), or interim controls in accordance with §35.1330(a) and (f); except for any bare soil that a current evaluation has found is not a soil-lead hazard.
- (4) Safe work practices, in accordance with sec. 35.1350, shall be used when performing any maintenance or renovation work that disturbs paint that may be lead-based paint.
- (5) Any encapsulation or enclosure of lead-based paint or lead-based paint hazards which has failed to maintain its effectiveness shall be repaired, or abatement or interim controls shall be performed in accordance with §§ 35.1325 or 35.1330, respectively.
- (6) Clearance testing of the worksite shall be performed at the conclusion of repair, abatement or interim controls in accordance with §35.1340.
- (7) Each dwelling unit shall be provided with written notice asking occupants to report deteriorated paint and, if applicable, failure of encapsulation or enclosure, along with the name, address and telephone number of the person whom occupants should contact. The language of the notice shall be in accordance with §35.125(c)(3). The designated party shall respond to such report and stabilize the deteriorated paint or repair the encapsulation or enclosure within 30 days.
- (b) Reevaluation. Reevaluation shall be conducted in accordance with this